

National Athletic Equipment Reconditioners Association

BOB FAWLEY
PRESIDENT

JASON SOARES
VICE PRESIDENT

GREG HEIDER
SECRETARY



www.naera.net

TONY BEAM
EXECUTIVE DIRECTOR

DREW DIXON
TREASURER

FRANK SCORDO
MEMBER AT LARGE

ATHLETIC EQUIP.REPAIR
MILWAUKEE, WI

ATHLETIC HELMET
ALTO, TX

ATHLETIC HELMET SE
TUSCUMBIA, AL

CAPITOL VARSITY SPORTS
OXFORD, OH

CONTINENTAL ATH. SUPPLY
GRIDLEY, CA

HARCO
FT. COLLINS, CO

INTEGRITY SPORT SERVICE
WADSWORTH, OH

MERCURY SPORTS
EVANSVILLE, IN

PRO LINE, INC.
MARIETTA, OH

RIDDELL /ALL AMERICAN
North Ridgeville, OH

SCHUTT RECONDITIONING
Salem, IL

SPORTSMAN'S RECOND
JOHNSTOWN, PA

STADIUM SYSTEM
CANAAN, CT

USA RECONDITIONING
GARFIELD, NJ

XENITH
DETROIT, MI

ATTENTION

August 29, 2024

It has been determined that the warning label placed on the exterior of football helmets reconditioned in 2024, could separate from the helmet under wet conditions. If during inspection of helmets in your inventory an exterior warning label is missing, this helmet should be taken out of play until the warning label is replaced.

Please contact your reconditioning representative for instruction.

NAERA recommends that during every football season or practice period, every helmet should be cleaned and inspected regularly by a school or organization staff member with knowledge of manufacturer recommendations.

Sincerely,

Tony Beam

Tony Beam, BA, E.S., CAA
Executive Director, NAERA